Weathertzatton Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/11011ME-0168
Work Order Type: Weatherization
Audit Name: 11011ME-0168

CLIENT INFORMATION

Client Name: Address:
Client ID: 11011ME-0168

Alt. Client ID: LOUDON

AGENCY INFORMATION

Agency: Mid-East Community Action Agency Agency Phone: (865) 248-8661

Address: P. O. Box 790

Company Name & License Number:	
Contractor's Signature:	
Contractor's Signature.	

COMMENT

BRUCE NIGH 865-384-1232 site built Natural Gas NO CERTIFIED FIRM/ RENOVATOR REQUIRED

DOE Weatherization Assistant Version 8.5.0 Page 1 of 7

Measure 1 Infiltration Redctn Inspected **Components** Comment 55* - SUNNY - NO WIND - RING OPEN - BASELINE-.8 AIR SEALS 10 PLUMBING & ELECTRICAL PENETRATIONS (SINKS & H20 HEATER) **Estimated** Actual # Material / Labor **Description / Comment Units Unit Cost** Total Qty **Unit Cost** Total Qty 1 Miscellaneous Infiltration Reduction Each 10 Supplies **LABOR** 2 Labor Each 1 Other Detail Sub Total: Measure Sub Total: Field Notes: Inspected Measure 2 DWH Tank Insulation **Components** Comment **Estimated** Actual # Material / Labor **Description / Comment Units Unit Cost** Total **Unit Cost** Total Qty Qty **DHW Tank Insulation** 1 1 Hot Water Each Equipment Each 2 Labor Labor Other Detail Measure Sub Total: Sub Total: Field Notes:

Measure 3 DW	/H Pipe Insulation			Componen	ts		ı	Inspecte
Comment				Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Actual Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1	Omit Oost	Total	Qiy		Total
i ilisulation	cost for 10' of wrap	Lacii	'					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes: Measure 4 Cle	an Heating Unit/Tune Ur	o Furnace		Componen				Inspecte
Measure 4 Cle	ean Heating Unit/Tune Սբ	o Furnace		Componen Estimated			Actual	Inspecte
Measure 4 Cle	ean Heating Unit/Tune Up	o Furnace	Qty	-		Qty		Inspecte
Measure 4 Cle Comment # Material / Labor				Estimated	1	Qty	Actual	
Measure 4 Cle Comment # Material / Labor 1 Heating Equipment	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
Measure 4 Cle Comment # Material / Labor 1 Heating Equipment	Description / Comment Tune Up Furnace	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Measure 4 Cle Comment # Material / Labor 1 Heating Equipment 2 Labor	Description / Comment Tune Up Furnace	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Measure 4 Cle Comment # Material / Labor 1 Heating Equipment 2 Labor	Description / Comment Tune Up Furnace	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Measure 4 Cle Comment # Material / Labor 1 Heating Equipment 2 Labor	Description / Comment Tune Up Furnace	Units Each Each	Qty 1 1	Estimated	1		Actual	
Measure 4 Cle Comment # Material / Labor 1 Heating Equipment 2 Labor	Description / Comment Tune Up Furnace	Units Each Each	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	

Report Run On: 5/21/2010

Measure 5 We	atherstrip Door (ea) x 2			Componen	ts		ı	Inspected
Comment Use Vir	nyl or rubber style,,,, then	caulk. 2 D	OORS	3				
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors	Weatherstrip Door	Each	2					
2 Labor	Labor	Each	1					
Other Detail						1		
			Measur	e Sub Total:]]	Sub Total:	
Field Notes:								
	(TERIOR WALLS ARE M/ . OF 944 SQFT	ASONITE		Componen	2,WAI 4,WAI 6,WAI	LL 3,W, LL 5,W, LL 7,W,	ALL ALL	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	944					7000
2 Labor	LABOR	Each	1					
Other Detail								
			Moasur	e Sub Total:]]	Sub Total:	
Field Meteor			Mcasar	c oub rotal.				
Field Notes:								

Measure 7 Pre	ssureRelief Piping Need	ded		Componen	ts			Inspected
Comment				-				
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	Pressure relief piping	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measure	e Sub Total:] ,	Sub Total:	
Manager 9 Van	vor Parrior Noodod			Company	40			Inspected
-	oor Barrier Needed	0 SQFT		Componen	ts			Inspected
(Ba	sement/CrawIspace) 70			Componen	ts			Inspected
(Ba				Componen Estimated			Actual	Inspected
(Ba Comment Use 6 r	sement/CrawIspace) 70		Qty	-		Qty		Inspected
(Ba	nil plastic UP 6" ON ALL S Description / Comment	SIDES		Estimated	<u> </u>	Qty	Actual	
(Ba Comment Use 6 r # Material / Labor 1 Health and Safety	mil plastic UP 6" ON ALL S Description / Comment Basement / crawlspace	SIDES <i>Units</i>	Qty	Estimated	<u> </u>	Qty	Actual	
(Ba Comment Use 6 r # Material / Labor 1 Health and Safety Items	plastic UP 6" ON ALL s Description / Comment Basement / crawlspace vapor barrier	SIDES <i>Units</i> SqFt	Qty 700	Estimated	<u> </u>	Qty	Actual	
(Ba Comment Use 6 r # Material / Labor 1 Health and Safety Items 2 Labor	plastic UP 6" ON ALL s Description / Comment Basement / crawlspace vapor barrier	SIDES <i>Units</i> SqFt	Qty 700	Estimated	<u> </u>	Qty	Actual	
(Ba Comment Use 6 r # Material / Labor 1 Health and Safety Items 2 Labor	plastic UP 6" ON ALL s Description / Comment Basement / crawlspace vapor barrier	SIDES <i>Units</i> SqFt	Qty 700	Estimated	<u> </u>	Qty	Actual	
(Ba Comment Use 6 r # Material / Labor 1 Health and Safety Items 2 Labor	plastic UP 6" ON ALL s Description / Comment Basement / crawlspace vapor barrier	Units SqFt Each	Qty 700	Estimated	<u> </u>		Actual	
(Ba Comment Use 6 r # Material / Labor 1 Health and Safety Items 2 Labor	plastic UP 6" ON ALL s Description / Comment Basement / crawlspace vapor barrier	Units SqFt Each	Qty 700	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
(Ba Comment Use 6 r # Material / Labor 1 Health and Safety Items 2 Labor Other Detail	plastic UP 6" ON ALL s Description / Comment Basement / crawlspace vapor barrier	Units SqFt Each	Qty 700	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
(Ba Comment Use 6 r # Material / Labor 1 Health and Safety Items 2 Labor Other Detail	plastic UP 6" ON ALL s Description / Comment Basement / crawlspace vapor barrier	Units SqFt Each	Qty 700	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Report Run On: 5/21/2010

				Componen	ts		1	Inspected
				Estimated			Actual	
1 Insulation De	escription / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
i ilisulation Re	epoint Floor Insulation	SqFt	617					
2 Labor La	abor	Each	1					
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
Field Notes:						1		
Measure 10 User-Sp Comment ATTIC - 617	_			Componen	ts		ı	Inspected
				Estimated			Actual	
# Material / Labor De	escription / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation AT	TTIC INSULATION	SqFt	617					
2 Labor La	abor	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:			Measur	e Sub Total:			Sub Total:	

Measure 11 Smart Thermostat					Componen	ts		Inspected			
C	Comment										
					Estimated	1		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total		
1	Heating Equipment	Smart Thermostat	Each	1							
2	Labor	Labor	Each	1							
(Other Detail						-				
				Measur	e Sub Total:] ;	Sub Total:			
	Field Notes:										
			Work O	rder Gra	nnd Total:		Gran	d Total:			